

INSPECTION REPORT

- 1). Name of the School : **ST. FRANCIS DE SALES SCHOOL**
2). Location : Satgaon, Narengi, P.O: Udyan Vihar, Guwahati- 781171, Assam
3). Type of Building : **RCC Building**
4). Year of Construction : **Block-A in 2001, Block-B in 2015**
5). Area/ Scope of work :

Block-A (G+3)

Ground Floor area= 2189.00 m²

- a) Class rooms
- b) Assembly area
- c) Library
- d) Court yard
- e) Administrative room
- f) Principal room
- g) Toilet for Boys, Girls
- h) Teachers room
- i) Lift, Staircase

1st floor Area=2302.00 m²

- a) Class rooms
- b) Hall
- c) Stage
- d) Court yard
- e) Computer room
- d) Toilet for Boys, Girls

2nd & 3rd floor Area=1498.00 m²

- a) Class rooms
- b) Court yard
- c) Computer room
- d) Toilet for Boys, Girls

Block-B (G+2)

Ground Floor area= 2177.70 m²

- a) Class rooms
- b) Assembly area
- c) Waiting area
- d) Toilet for Boys, Girls
- e) Staff room
- f). Lift, Staircase


1st floor Area=2024.70 m²


- a) Class rooms
- b) Lab
- c) Toilet for Boys, Girls
- d) Staff room

2nd floor Area=2164.02 m²

- a) Class rooms
- b) Library
- c) Toilet for Boys, Girls
- d) Staff room

The School is visited on 28.11.2022. No physical disorder is observed and found structurally fit. This certificate is valid for 2 years from date of issue. Moreover, in case of major earthquake etc, the Structural fitness will be re-ascertained.


Junior Engineer, PWD
Dispur Territorial Building
Sub Division, Guwahati-I


Asstt. Executive Engineer, PWD
Dispur Territorial Building
Sub Division, Guwahati-I


Executive Engineer, P.W.D.
Dispur & Guwahati East
Territorial Building Division
Guwahati-I